


Cutting the Cording Ends - Step 25



Step D stitching- 8.5" from center

Step C marks- 4.75" from center

Step B centermark

Step E stitching-